

Property Details for moving walk back - 10/9/2013

Address	Side of the Street	Property Type	Type of Encroachment	Other concerns:
2157 Glenwood	R	Private	None	Large grade change behind existing walk, would need retaining wall in order to move the walk back.
2160 Glenwood	R	Private	None	Large grade change behind existing walk, would need retaining wall in order to move the walk back.
2202 Glenwood	L	Private	Established Hedge Row along the entire property. Would need to be eliminated.	
721 Bancroft	R	Private/Duplex	Landscaping Flowers and steps leading to the porch	The house is only about 5' behind the R/W. It would be difficult to move the walk back and maintain steps onto the porch.
717 Bancroft	R	Private/Duplex	Steps Leading to the porch	The house is only about 5' behind the R/W. It would be difficult to move the walk back and maintain steps onto the porch.
2155 Robinwood	R	Private	None	
2152 Robinwood	R	OWE Commons	Flowers and Landscaping	Moving the walk back would reduce the planting bed by about 5'-6'.
2210 Robinwood	L	Private	Existing Landscaping (Bushes, Brush and Cedar Trees) and steps leading onto the property.	Large grade change behind existing walk. Would need a retaining wall.
2159 Scottwood	R	Multi-Unit	Landscaping.	The building and brick wall is only 1' behind the R/W.
2160 Scottwood	R	Private	Cut stone retaining wall and bushes	Large Grade Difference.
2200 Scottwood	L	Multi-Unit	Wooden Planters, Wrought Iron fence, established landscaping and steps.	Large grade difference that would require a retaining wall. The building is close to the R/W.
633 Bancroft	R	Private	Landscaping and curb wall	Large Grade change.
625 Bancroft	R	Private	Wood retaining walls and established landscaping.	
623 Bancroft	R	Private	Wrought Iron Fence, Shrubs	
620 Bancroft	L	Business	None	
2205 Parkwood	L	Private	Steps to the building and wrought iron fence.	
2154 Parkwood	R	Private	Shrubs	Large grade change would require a retaining wall
2208 Parkwood	L	Church	Wrought Iron Fence with brick posts. Hedge row.	Building is very close to the R/W. Large grade change in front of the building would require a retaining wall.
531 Bancroft	R	Multi-Unit	Retaining wall	
527 Bancroft	R	Multi-Unit	none	
519 Bancroft	R	Multi-Unit	None	Large tree just inside the R/W would probably need to be cut in order to move the walk back.